

John P. Zager General Manager Union Oil Company of California 3800 Centerpoint Drive Suite 100 Anchorage, AK 99503 Tel 907 263 7815 Fax 907 263 7897 Email jzager@chevron.com

RECEIVED

RECEIVE

MAR 0 5 2012

Nastewat y Day of the Pergram

DEC Division of Valor Quality

March 2, 2012

Director, Office of Compliance and Enforcement Attention: Data Entry Staff United States Environmental Protection Agency, Region 10 1200 Sixth Avenue, OCE-133 Seattle, WA 98101

RETURN RECEIPT REQUESTED
CERTIFIED MAIL: 91 7011 2970 0001 9243 7751

Re: REVISED Discharge Monitoring Reports

NPDES Permit No. AKG-31-5000

To whom it may concern:

Union Oil Company of California (UOCC) operates the Dolly Varden Platform (AKG-31-5009), Grayling Platform (AKG-31-5016), King Salmon Platform (AKG-31-5008), Steelhead Platform (AKG-31-5019), and Trading Bay Production Facility (AKG-31-5002) in Cook Inlet, Alaska. In our efforts to assure compliance with the Cook Inlet NPDES General Permit AKG-31-5000 and applicable laws and regulations, UOCC identified Discharge Monitoring Reports (DMRs) that require revision. None of the changes result in any violations of permit conditions.

A list of revised DMRs is presented below in Table 1. Both the revised DMR and photocopies of the original DMR pages have been included. Consistent with the authorization in your e-mail from September 16, 2010, this letter certifies all of the 26 pages of DMRs attached to this letter.

If you have any questions, please direct them to Mr. Rodney Bailey at (432) 687-7123 or via email at bailerg@chevron.com.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Director, Office of Compliance and Enforcement US Environmental Protection Agency March 2, 2012 Page 2

Sincerely,

John P. Zager

cc: ADEC / Certified Mail 91 7011 2970 0001 9243 7768

Director, Office of Compliance and Enforcement US Environmental Protection Agency March 2, 2012 Page 3

Table 1. DMR Revisions

February 2011

Facility	Parameter	Reason for Revision
Grayling Platform (AKG-31-5016)	Workover Fluids (017)	Estimated amount of workover fluids sent to Trading Bay Production Facility were not reported.
Trading Bay Production Facility (AKG-31-5002)	Produced Water and Sand (015)	Estimated workover fluid flow rate was not reported.

April 2011

Facility	Parameter	Reason for Revision
Grayling Platform (AKG-31-5018)	Workover Fluids (017)	Estimated amount of workover fluids sent to Trading Bay Production Facility was misreported.
Trading Bay Production Facility (AKG-31-5002)	Produced Water and Sand (015)	Estimated well treatment/workover fluid flow rate was misreported.

May 2011

		1
Facility	Parameter Parameter	Reason for Revision
King Salmon Platform (AKG-31-5008)	Workover Fluids (017)	Estimated amount of workover fluids sent to Trading Bay Production Facility was misreported.
Trading Bay Production Facility (AKG-31-5002)	Produced Water and Sand (015)	Estimated workover fluid flow rate was misreported.

June 2011

Facility	Parameter	Reason for Revision
King Salmon Platform (AKG-31-5008)	Workover Fluids (017)	Estimated amount of workover fluids sent to Trading Bay Production Facility was misreported.
Steelhead Platform (AKG-31-5019)	Workover Fluids (017)	Estimated amount of workover fluids sent to Trading Bay Production Facility was misreported.
Trading Bay Production Facility (AKG-31-5002)	Produced Water and Sand (015)	Estimated workover fluid flow rate was misreported.

December 2011

Facility	Parameter	Reason for Revision
Dolly Varden Platform (AKG-31-5009)	Non-Contact Cooling Water (009)	Waterflooding discharges for December 2011 should have been considered Non-Contact Cooling Water since the waterflood portion of the commingled waste stream was shut-in and there were no chemical additives. Volumes were corrected after original December 2011 DMR submittal.
Dolly Varden Platform (AKG-31-5009)	Waterflood (014)	Waterflooding discharges for December 2011 should have been considered Non-Contact Cooling Water since the waterflood portion of the commingled waste stream was shut-in and there were no chemical additives. Therefore there were no waterflood discharges in December 2011.

Director, Office of Compliance and Enforcement US Environmental Protection Agency March 2, 2012 Page 4

bcc: Susan Saupe, CIRCAC

Dolly Varden Lead Operators
Grayling Lead Operators
King Salmon Lead Operators
Steelhead Lead Operators

Trading Bay Production Facility Lead Operators

HES 2011 NPDES DMR Facility Files
HES 2011 NPDES DMR REGIONAL File

NATIONAL PALLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) DISCHARGE MONITORING REPORT (DMR)

COPY

Form Approved
OMB No. 2040-0004

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different)

NAME: UNION OIL COMPANY OF CALIFORNIA (UNOCAL)

ADDRESS: P.O. BOX 196247

ANCHORAGE, AK 99519-6247

FACILITY: TRADING BAY TREATMENT FACILITY

LOCATION: COOK INLET, Alaska

ATTN: JOHN ZAGER, GENERAL MANAGER

AKG315002 PERMIT NUMBER

FROM

015-A
DISCHARGE NUMBER

| MONITORING PERIOD | | MM/DD/YYYY | MM/DD/YYYY | | 05/01/2011 | TO | 05/31/2011 |

DMR Mailing ZIP CODE: 99519

MINOR (SUBR 02)

PRODUCED WATER AND SAND

External Outfall

No Discharge

PARAMETER		QUAN	QUALITY OR LOADING QUALITY OR CONCENTRATION				NO. EX	FREQUENCY OF ANALYSIS	SAMPLE TYPE		
		VALUE	VALUE	UNITS	VALUE	VALUE	VALUE	UNITS			
рН	SAMPLE MEASUREMENT	*****	*****	******	NA	*****	NA	NA	NA	NA	NA
00400 V 0 See Comments	PERMIT REQUIREMENT	*****	*****	*****	6 MINIMUM	*****	9 MUMIXAM	SU		Monthly	GRAB
PΗ	SAMPLE MEASUREMENT	******	*****	*****	6.9	*****	7.3	su	0	Weekly	GRAB
00400 W 0 See Comments	PERMIT REQUIREMENT	4++++	*****	*****	6 MINIMUM	*****	9 MUMIXAM	SU		Weekly	GRAB
Oil and grease	SAMPLE MEASUREMENT	****	*****	*****	****	NA	NA	NA	NA	NA	NA
03582 T 0 See Comments	PERMIT REQUIREMENT	*****	314141	*****	*****	29 MO AVG	42 DAILY MX	mg/L		Weekly	GRAB
Oil and grease	SAMPLE MEASUREMENT	*****	*****	*****	457454	23	33	mg/L	0	Weekly	COMP24
03582 U 0 See Comments	PERMIT REQUIREMENT	*****	*****	*****	*****	29 MO AVG	42 DAILY MX	mg/L		Weekly	COMP24
Flow, in conduit or thru treatment plant*	SAMPLE MEASUREMENT	3.329714	3.627330	Mgal/d	*****	****	*****	*****	NA	Monthly	ESTIMA
50050 1 0 Effluent Gross	PERMIT REQUIREMENT	Req. Mon. MO AVG	Req. Mon. DAILY MX	Mgai/d	*****	*****	*****	*****		Monthly	ESTIMA
Produced water, free oil	SAMPLE MEASUREMENT	****	NA.	NA	****	ee	*****	*****	NA	NA	NA
79834 1 0 Effluent Gross	PERMIT REQUIREMENT	*****	Req. Mon. MO TOTAL	occur/mo	****	849.6.4	*****	******		Daily	VISUAL

NAME/TITLE PRINCIPAL EXECUTIVE OFFICER	Legisles under princip of loss that they do assent and all attachments more prepared assets are absolved or cupervisive accordance with a system designed to asserv that qualified personnel properly pather and evolunts the		TEL	EPHONE	DATE
John Zager, General Manager Mid Continent/Alaska Business Unit	chirantive schoidtal Hased on ny sugare of the present or persons who manage the system, of those persons directly responsible for gatherine the information, the information relegation is, he the best of my know-bodye and yelled; tree, received, and complete. Law ower that there are significant penaltives he solutionizing lake	SIGNATURE OF PRINCIPAL EXECUTIVE OFFICER	(907) 276-7600		06/15/2011
TYPED OR PRINTED	enformation, including the probability of fine and introcurement for knowing violetions.		AREA Code	NUMBER	MM/DD/YYYY

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

NO DISCHARGE OF PRODUCED SAND IS ALLOWED

T = GRAB SAMPLE

U = COMPOSIT SAMPLE

V = DISCHARGE < 1 MGD (PREVIOUS MONTHS AVG RATE)

W = DISCHARGE > 1 MGD (PREVIOUS MONTH'S AVG RATE)

* Flow rates include deck drainage from Dolly Varden, Grayling, King Salmon, Monopod, and Steelhead Platforms.

Estimated workover fluid flow rate: 0.055742 mgd

NATIONAL PALLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)

DISCHARGE MONITORING REPORT (DMR)

REVISED 3/2/2012 Form Approved OMB No. 2040-0004

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different)

NAME:

UNION OIL COMPANY OF CALIFORNIA (UNOCAL)

ADDRESS: P.O. BOX 196247

ANCHORAGE, AK 99519-6247

FACILITY: TRADING BAY TREATMENT FACILITY LOCATION: COOK INLET, Alaska

ATTN: JOHN ZAGER, GENERAL MANAGER

AKG315002 PERMIT NUMBER

FROM

015-A
DISCHARGE NUMBER

DMR Mailing ZIP CODE: 99519

MINOR (SUBR 02)

PRODUCED WATER AND SAND

External Outfall

No Discharge

PARAMETER		QUANTITY OR LOADING		QUALITY OR CONCENTRATION			NO. EX	FREQUENCY OF ANALYSIS	SAMPLE TYPE		
TANAMETER		VALUE	VALUE	UNITS	VALUE	VALUE	VALUE	UNITS			
РН	SAMPLE MEASUREMENT	*****	****	*****	NA	******	NA	NA	NA	NA	NA.
00400 V 0 See Comments	PERMIT REQUIREMENT	******	*****	*****	8 MINIMUM	*****	9 MAXIMUM	SU		Monthly	GRAB
pH	SAMPLE MEASUREMENT	\$20°04.1	*****		6.9	******	7.3	SU	0	Weekly	GRAB
00400 W 0 See Comments	PERMIT REQUIREMENT	******	*****	*****	6 MINIMUM	******	9 MAXIMUM	SU		Weekly	GRAB
Oil and grease	SAMPLE MEASUREMENT	*****	参加を人が取	*****	****	NA	NA	NA	NA	NA	NA
03582 T 0 See Comments	PERMIT REQUIREMENT	44444	*****	44444	40444	29 MO AVG	42 DAILY MX	mg/L		Weekly	GRAB
Oil and grease	SAMPLE MEASUREMENT	*****	*****	*****	A+4+44	23	33	mg/L	0	Weekly	COMP24
03582 U 0 See Comments	PERMIT REQUIREMENT	*****	*****	*****	****	29 MO AVG	42 DAILY MX	mg/L		Weekly	COMP24
Flow, in conduit or thru treatment plant*	SAMPLE MEASUREMENT	3.329714	3.627330	Mgal∕d	****	*****	#####		NA	Monthly	ESTIMA
50050 1 0 Effluent Gross	PERMIT REQUIREMENT	Req. Mon. MO AVG	Req. Mon. DAILY MX	Mgal/d	****	*****	****	*****		Monthly	ESTIMA
Produced water, free oil	SAMPLE MEASUREMENT	****	NA	NA	****	*****	*****	*****	NA	NA	NA
79834 1 0 Effluent Gross	PERMIT REQUIREMENT	*****	Req. Mon. MO TOTAL	occur/mo	*****	*****	44494	474749		Daily	VISUAL

NAME/TITLE PRINCIPAL EXECUTIVE OFFICER	rabets 1800 with the second of Steen as wrong nest destitien beautiful blobett, Witten with examine		TEL	LEPHONE	DATE
	information submitted. Hused in my inquire of the person or persons who manage the mostern, or those persons directly responsible for gathering the information, the internation submitted is, to the best of my knowledge ar		(907)	276-7600	06/15/2011
	belief, true accurate, and complete. Law aware that there are segnificant possition for submitting faint	SIGNATURE OF PRINCIPAL EXECUTIVE OFFICER		2107000	00,10,2011
TYPED OR PRINTED	information, sactuding the possibility of the and improvinges for knowing violations.	OR AUTHORIZED AGENT	AREA Code	NUMBER	MM/OD/YYYY

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

NO DISCHARGE OF PRODUCED SAND IS ALLOWED

T = GRAB SAMPLE

U = COMPOSIT SAMPLE

V = DISCHARGE < 1 MGD (PREVIOUS MONTHS AVG RATE) W = DISCHARGE > 1 MGD (PREVIOUS MONTH'S AVG RATE) * Flow rates include deck drainage from Dolly Varden, Grayling, King Salmon, Monopod, and Steelhead Platforms.

Estimated workover fluid flow rate: 0.034003 mgd

3/2/2012 Revision Estimated workover fluid flow rate was misreported